



Bank Stability and Composition on the Connecticut River in northern Dalton, NH.



0 1500 3000 Feet



Map prepared by:



With support from:



Map source: Basemap - USGS DRG quads, VCGI 2004
Field survey data - Field Geology Services 2004
Map Prepared December 2005