



# Bank Stability and Composition on the Connecticut River in southern Columbia, NH.



0 1500 3000 Feet



Map prepared by:



Map source: Basemap - USGS DRG quads, VCGI 2004  
Field survey data - Field Geology Services 2004  
Map Prepared December 2005

With support from:

